

SWAGING MANDRELS FOR 4500-SERIE FITTINGS

9014-00

Product info

To control that the swaging has resulted in the right internal collapse. GO-side should pass through the fitting to make sure that the swaging is not overdone.

Product info2

The STOP-side should stop in the middle of the tail to ensure that the swaging is sufficient.

Type

Machine accessories

| Part no. | Dimension |
|----------|-----------|
| 90140006 | 3/8" |
| 90140008 | 1/2" |
| 90140010 | 5/8" |
| 90140012 | 3/4" |
| 90140016 | 1" |